

	SC = Press tool with Cylinder	SH = Hollow piston press tool
免润滑	★ ★ ★	★ ★ ★
低维护	★ ★ ★	★ ★
紧凑	★ ★	★ ★ ★
重量轻	★ ★	★ ★ ★
可访问性	★ ★ ★	★ ★
耐污垢度	★ ★ ★	★
持续性	★ ★ ★	★ ★
价格	★ ★	★ ★ ★
适应性	车间	移动



SC 6 | SC 6 S



SH 6



SH 10 i
SH 10 i XL




SC 12 i

	SC 6 Ecoline* SC 6	SC 6 S Ecoline SC 6 S	SH 6 Ecoline* SH 6 Mobileline SH 6 S Ecoline SH 6 S Mobileline	SH 10 i Ecoline SH 10 i SH 10 i XL Ecoline SH 10 i XL*	SC 12 i A SC 12 i C.2*
	2,000/200	2,800/280	2,400/240; 2,800/280	2,800/280	3,700/370
	2"	2"	2"	2"	3"
	1½"	2"	1½" / 2"	2"	3"
	3"	3"	3"	4"	4"
	102	102	102	145	145
	110/4.33	110/4.33	110/4.33	126/4.96	126/4.96
	+45	+45	+41; +45;	+45; +61	+61
	239-xx/266	239-xx/266	239-xx/266	239-xx/237L	239/237L
	车间	车间/移动	车间/移动	车间	车间

QDS 239 B

QDC 239.5



使用QDC系统快速轻松地更换模具。

移动使用

